

FIELD INSPECTION REPORT

Date of Inspection :	3.11.2020	District:	Katihar
Division :	Barrson	Length (km):	3.75
Name of the Road:	Patol to Maohar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21105608037
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S/U
f)	Contraction Joints provided or not (CC Pavement)		Yes/No ✓ yes
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓ SRI
Unsatisfactory (U)	

3.11.2020
(Signature)

NAME:

REDMI NOTE 6 PRO
MI DUAL CAMERA