

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020		District: Kishanganj
Division : Kishanganj - 2		Length (km): 6.610 Kms
Name of the Road: Taplu to Garwardanga		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 21205908044.
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U V
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Flood damaged heavily.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	

NAME:

(Signature)

3/12/20
AB