## FIELD INSPECTION REPORT

Date o	of Inspection: O	3.12.2020	District: Sayan	
Divisio		chapra-1	Length (km): 9,001, 0	
Name	of the Road: Re	pair of road fro	m Karinger Bandh wad I	is Jaglat Ro
Scheme/Programme: MAINTENANCE Package No.:		MAINTENANCE	MR13054	- wat
			Road Id Ng.: 31306208	089
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		-
	Company of the contract of the	THE TWO IS A PART OF THE PART	p gradation/ Maintenance	
SI. No.	A STATE OF THE STATE OF	Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			\S/U
b)	Condition of Surfacing			\\$/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free aggregates in ca	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Furniture			
$\begin{vmatrix} 1 \\ 1 \end{vmatrix}$	Whether sign b tones/Pavement	oards/informatory/ca road markings are pr	utionary Board/km & 200m ovided and maintained	Yes/No
	ompliance His	fory:		are Var
) S	tatus of ATR's &	& any others		-

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

Scanned with CamScanner