

# FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District:	Saran
Division :	Chapra-1	Length (km):	6.00 km.
Name of the Road:	Repair of road from Kadna Bazar to Dhanaura Bazar		
Scheme/Programme:	MAINTENANCE	MR 13059	
Package No.:		Road Id No.:	31306208091
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/✓U
c)	Riding Quality	S/✓U
d)	Road Camber	S/✓U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: Palmile  
03/12/2020

DESIGNATION:

28/12/2020  
A.B. (Signature)

Palmile  
03/12/2020