

# FIELD INSPECTION REPORT

|                                                                |  |                            |
|----------------------------------------------------------------|--|----------------------------|
| Date of Inspection : 03-12-2020                                |  | District: Chhota (Basau)   |
| Division : Chhota-1                                            |  | Length (km): 8.610         |
| Name of the Road: Repair of road from Manghi to Nandpur Banwar |  |                            |
| Scheme/Programme: MAINTENANCE                                  |  | MR - 2024                  |
| Package No.:                                                   |  | Road Id No.: 3130 62080 92 |
| Status of the Project: Ongoing/Completed/Under Maintenance     |  |                            |
| Work is a case of: New Connectivity/Up gradation/ Maintenance  |  |                            |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      |          |
| a)      | Road Junction condition                                                                                              | ✓ S/U    |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U    |
| c)      | Riding Quality                                                                                                       | ✓ S/U    |
| d)      | Road Camber                                                                                                          | ✓ S/U    |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓ |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No |
| 2.      | <b>Cross Drainage</b>                                                                                                |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U  |
| 3.      | <b>Road Furniture</b>                                                                                                |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| 4.      | <b>Compliance History</b>                                                                                            |          |
| a)      | Status of ATR's & any others                                                                                         | —        |

Overall Rating :

|                                               |   |
|-----------------------------------------------|---|
| Satisfactory (S)                              |   |
| ✓ Satisfactory but requires Improvement (SRI) | ✓ |
| Unsatisfactory (U)                            |   |

NAME:

DESIGNATION:

03/12/2020  
J.B.

29.12  
3/12/2020  
A.B.

(Signature)  
3/12/2020