## FIELD INSPECTION REPORT

Date of	Inspection:	63-17.7076	District: SARA	N	
Divisio	n: (	CHAPRA-I	7 11 11	5 Km	
Name o	of the Road:	NH-19 7 7	VAIT 413	3 KM	
Scheme	/Programme:	MAINTENANCE	MR- 3054		
Package No.:				1000-00	
Status of the Project:		Road Id No.: 31306208098 Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.	And the second second	Parameters to	~	Remarks	
1.	Pavement	ACMINITED TO STATE OF THE PARTY			
a)	Road Junction	condition		S/U	

		Remarks		
1.	Pavement			
a)	Road Junction condition	,S/U		
b)	Condition of Surfacing	S/U		
c)	Riding Quality	S/U		
d)	Road Camber	S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	1/1	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI) SRI

Unsatisfactory (U)

NAME:

DESIGNATION:

Scanned with CamScanner