## FIELD INSPECTION REPORT

Date of It	spection: 03.12.2020 District: Siwan	
Division :	Si Wan-01 Length (km): 2.500 km	contradity (c) (c) which committee and a contradition
	he Road: Schuli de francolipute Mahpus	and a second arrange lands on
	rogramme: MAINTENANCE MR 3054	
Package	Road Id No.:	
Status of	the Project: Ongoing/Completed/Under Maintenance	
Work is:		Remarks
Sl. No.	Parameters to be checked	Remarks
1.	Payement	A Contract of the Contract of
a)	Road Junction condition	√s/U 3
b)	Condition of Surfacing	√s/U S
c)	Riding Quality	VS/U S
	Road Camber	SU S
(e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No Prevision
D	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Wes/No yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	VS/SRI/U 9
b)	Condition of Abutment & Wing walls, Slab in RCC culverts 6	SISRIAU No provision
c)	Condition of railings/slab/approach for Bridges	S/SRL/U NA
	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	VYes/No 702
4.	Compliance History	
a).	Status of ATR's & any others	NO ATR
Lamberger	U.D.	
Over	all Rating : Satisfactory (S)	3
	Satisfactory but requires Improvement (SRI)	and the second of the second o
	Unsatisfactory (U)	An application of the second o
	Polination (8	curel 31121020 JE ignature)

A-B

NAME: RAVINDRA KUMAR

MANDAL