

FIELD INSPECTION REPORT

Date of Inspection : 21/12/2020	District: Siwan	
Division : RWD Siwan-2	Length (km):	
Name of the Road: Chhatiya Hanuman Mandir to Mahawal Bazar		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.:	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance	On going	
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	In progress. S/U
b)	Condition of Surfacing	In progress S/U
c)	Riding Quality	In progress S/U
d)	Road Camber	Do Do S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	In progress Yes/No
g)	Compaction of flank/slope & raincuts if any	In progress Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

31/12/20
A.E.
कावेपालक अभियंता,
समाज कार्य विभाग,
प्रमण्डल सिवान-2

31/12/20
(Signature) J-G