

MR (3054)

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020		District: SIWAN
Division : SIWAN-2		Length (km): 5.240 km
Name of the Road: HARPUY TO Datar (Part - I)		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S' S/U
b)	Condition of Surfacing	S' S/U
c)	Riding Quality	S' S/U
d)	Road Camber	S' S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

Gallagher
3/12/2020
A.E.

(Signature)

3/12/2020
JE

for
2/12/20
Executive Engineer
Rural Work Department
Work Division-2

Scanned by CamScanner

Scanned with CamScanner