

# FIELD INSPECTION REPORT

Date of Inspection : 02/12/20	District: SIWAN	
Division : SIWAN - 2	Length (km): 7.85 km	
Name of the Road: Tilmapur to Siswa via Bishunpura		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition S	S/U
b)	Condition of Surfacing U	S/U
c)	Riding Quality U	S/U
d)	Road Camber S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any Raincuts found	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting SRI	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S	S/SRI/U
c)	Condition of railings/slab/approach for Bridges SRI	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Not Maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

DESIGNATION:

2/12/20  
A.E.  
2/12/20  
मुख्यपालक अभियंता  
राज्य कार्य विभाग  
प्रमण्डल सिवान-2

AI  
02/12/20  
J.E.  
(Signature)