

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Gopalganj
Division : Halhita	Length (km): 11.250 km
Name of the Road: Repair of road from Dubauliya to Jagtoli	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	SU/U
a)	Road Junction condition	SU/U
b)	Condition of Surfacing	SU/U
c)	Riding Quality	SU-U
d)	Road Camber	SU-U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NO
g)	Compaction of flank/slope & raincuts if any	Yes/No - NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - NO
4.	Compliance History	U
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)  03/12/2020

NAME: MANOJ KUMAR

DESIGNATION: A.E. R.W.D. Halhita