

# FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020		District : East Champaran
Division : RWP Chakia		Length (Km): 1.80 km
Name of the Road : NH 28 to Tappur		
Scheme/Programme : MAINTENANCE		
Package No.: NA		Road ID No.: 31708408030
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	No
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	SRI
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

Remarks:- Informatory board painting required.

NAME :

DESIGNATION :

ABW  
02/12/2020

02/12/2020

(Signature)  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमण्डल, चकीया