

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020 District : East Champaran

Division : RWD Chalcia Length (Km): 2.0 km

Name of the Road : NH 28 Se Madhuchhapra

Scheme/Programme : MAINTENANCE

Package No.: NA Road ID No.: 31708408032

Status of the Project : Ongoing/Completed/Under Maintenance

Work is a case of : New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2,	Cross Drainage	-
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	Yes
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : Satisfactory (S)
Satisfactory but requires improvement (SRI)
Unsatisfactory (U)

02/12/2020
JF

02/12/20
mt

(Signature)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, चकीया

NAME :
DESIGNATION :