FIELD INSPECTION REPORT

The same of the sa	The second secon	THE BUILD HAVE LOT	CHICKI	
Date of Inspection: 03 - 12 - 20 20 Distr			District: East	Champonas
Division: Charles'a Length (Km):			Length (Km): 60	
Name of the Road: PWD Road Sattar Ghat Road to Ra				Rampur Koras
Scheme/Programme: MAINTENANCE				
Package No.: NA Road ID No.: 317089			08042	
Status of	the Project :	Ongoing/Completed/U	Inder Maintenance	
Work is a case of : New Connectivity/Up Gradation/ Maintenance				
SI. No.	Parameters to be checked			Remarks
1,	Pavement			
a)	Road Junction condition			Yes 'S'
b)	Condition of Surfacing			Yes's'
c)	Riding Quality			ري مد
d)	Road Camber			2
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			No
f)	Contraction Joints provided or not (CC Pavement)			-
g)	Compaction of flank/slope & raincuts if any			
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			_
c)	Condition of railings/slab/approach for Bridges			
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			Yes
4,	Compliance History			
a)	Status of ATR's & any	others		
為其		2 4'- f40m; (C)		(5)
	Overall Rating :	Satisfactory (S) Satisfactory but requires improvement (SRI)		
		Unsatisfactory (U)		
	_			
	(Signature)			e)
	NAME:	100	ı	
	DESIGNATION :	Er Xo'		