FIELD INSPECTION REPORT Date of Inspection: 03 - 12 - 20 20 East champeras District: Charlera Division: Length (Km): 2.00 km Name of the Road : PIND Satter Ghat Road to Tappur Scheme/Programme : MAINTENANCE Package No.: MA Road ID No.: 31708408043 Status of the Project : Ongoing/Completed/Under Maintenance Work is a case of : New Connectivity/Up Gradation/ Maintenance Parameters to be checked Remarks SI. No. Pavement 1, a) Road Junction condition b) Condition of Surfacing c) Riding Quality 's ' d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in No e) case of CC Pavement. Contraction Joints provided or not (CC Pavement) f) Compaction of flank/slope & raincuts if any g) Cross Drainage 2. Condition of head walls in Hume pipe culverts including its painting Yes a) Condition of Abutment & Wing walls, Slab in RCC Culverts b) Condition of railings/slab/approach for Bridges c) Whether sign board/informatory/cautionary Board/Km & 200m Yes 3, Stones/Pavement road markings are provided and maintained a) Compliance History 4, Status of ATR's & any others a) Overall Rating

Satisfactory but requires improvement (SRI) Unsatisfactory (U)

NAME:

DESIGNATION:

5.72 2020

(Signature)