

FIELD INSPECTION REPORT

Date of Inspection :	02.12.20	District:	East Champaran
Division :	Raxaul	Length (km):	7.0 km
Name of the Road:	REO Road Bhawanban to Pakhi Andhra		
Scheme/Programme:	MAINTENANCE '3054'		
Package No.:		Road Id No.:	31078508037
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	M.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	M.A Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	M.AS/SRI/U
c)	Condition of railings/slab/approach for Bridges	M.AS/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	M.A

Overall Rating :

Satisfactory (S)	11 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sanjay Kumar
21/12/20
(Signature)

NAME: Sanjay Kumar
DESIGNATION: Assistant Engineer