FIELD INSPECTION REPORT

-	MANAGEMENT .	3 12 2020	District: Madhubani	
Division: Madhubani Length (km): 2,650 K			и,	
		3 hagwati Pur	to Baluaha	
THE RESIDENCE OF THE PARTY OF T	Programme:	MAINTENANCE		
ackage No.:		Road Id No.:		*
			d/Under Maintenance	
	a case of:	A STATE OF THE STA	Up gradation/ Maintenance	
Sl. No.	No. Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			s/u S
b)	Condition of Surfacing			S/U S
c)	Riding Quality			S/U S
d)	Road Camber			s/u S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
1/31,302	Cross Drain	inge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)				Yes/No
四分本版	Compliance History			NO AT
a)	Status of A	Status of ATR's & any others Sur face is good		
Overall Rating				5
		Satisfactory (S) ut requires Improvement (SRI)	-
		Satisfactory bu	It tedance rucker comment (220)	-

NAME: Ashok proceed simply DESIGNATION: AE, pandaul (Signature)

Way Andaul San

May May Now ar San

May May Now ar San