FIELD INSPECTION REPORT

Date of	Inspection: 0	13-12-2020	District: Martin La	
Division:			Laghuban	4
Name of		epair of Ruad LO		
Scheme	Programme:	MAINTENANCE	33 TO DERHAL	
Package	No.:		Road Id No.: 3/90970802	
Status of the Project:		Ongoing/Completed	/Under Maintenance	22
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.	Well of the second	Parameters to		Remarks
100	Payamant			Charles Supering

Sl. No.	Parameters to be checked			
1.	Payement			
a)	Road Junction condition	- S/U		
b)	Condition of Surfacing	S/U		
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage			
a)	Condition of head-walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture S/SRI/U			
a)_	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
-4.	Compliance History			
a) _	Status of ATR's & any others	No		

Overall Rating

Satisfactory (S)	G-	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: CHITRANJAN RAHUL

DESIGNATION: J.E, Basopath