

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Araon
Division :	Araon	Length (km):	11.40 km
Name of the Road:	Darsana to Chabai via Hansa Gola		
Scheme/Programme:	MAINTENANCE		
Package No.:	—	Road Id No.:	21206000843
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank/slope & raincuts if any	Yes/No Rain cut ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

NAME:
TRIBHUVAN HATH
J.E.

03.12.2020
A.E.
Rajesh Kr Mandal

03/12/2020
(Signature)