


# FIELD INSPECTION REPORT

|                         |  |               |                        |
|-------------------------|--|---------------|------------------------|
| Date of Inspection :    | 03.12.2020   | District :    | MUNGER                 |
| Division :              | Kharagpur - Tarapur  | Length (Km) : | 2.50 Km                |
| Name of the Road :      | PND Path Kharagpur-Jamui to Kharai Path  |               |                        |
| Scheme/Programme :      | MAINTENANCE ✓ MR-305U (O/D)  |               |                        |
| Package No. :           |  | Road Id No. : | 20803800832 Project 1D |
| Status of the Project : | Ongoing/Completed/Under Maintenance ✓  |               |                        |
| Work is a case of :     | New Connectivity/Up gradation/Maintenance  |               |                        |
| Sl. No.                 | Parameters to be checked   | Remarks       |                        |
| 1                       | Pavement   |               |                        |
| a)                      | Road Junction condition  | ✓S/U          |                        |
| b)                      | Condition of Surfacing   | ✓S/U          |                        |
| c)                      | Riding Quality   | ✓S/U          |                        |
| d)                      | Road Camber  | ✓S/U          |                        |
| e)                      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No       |                        |
| f)                      | Contraction Joints provided or not (CC Pavement)   | ✓Yes/No       |                        |
| g)                      | Compaction of flank/slope & raincuts if any  | ✓Yes/No       |                        |
| 2                       | Cross Drainage   |               |                        |
| a)                      | Condition of head walls in Hume pipe culverts including its painting   | S/SRI/U       | } NA                   |
| b)                      | Condition of Abutment & Wing walls, Slab in RCC culverts   | S/SRI/U       |                        |
| c)                      | Condition of railings/slab/approach for Bridges  | S/SRI/U       |                        |
| 3                       | Road Furniture   |               |                        |
| a)                      | Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No       |                        |
| 4                       | Compliance History   |               |                        |
| a)                      | Status of ATR's & any others   | NO            |                        |

Overall Rating :

|   |  |
|---|--|
| Satisfactory (S) ✓                          |  |
| Satisfactory but requires Improvement (SRI) |  |
| Unsatisfactory (U)                          |  |

NAME : Ram Darsan Ram  
DESIGNATION : J. E.

  
03/12/2020  
(Signature)