## FIELD INSPECTION REPORT

Date of Inspection: 03-12-2020			District: James	
Name of the Road: Dlane of the			Length (km): 3. (0	
	the Road: Programme:	Dhamus to (	roundpur pare	
Package		MAINTENANCE	(OLD MK)	
	the Project:	Ongoing/Complete	Road Id No.: 2080420082	24
Work is a case of:		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance		
SI. No.		Parameters to		Remarks
1.9	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			,S/U
d)	Road Camber			\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR	's & any others	6	

Overall Rating

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	100
Unsatisfactory (U)	

NAME: Ansur Rahmoro DESIGNATION: Greculive Engineer