

FIELD INSPECTION REPORT

Date of Inspection:	3-12-2020	District:	Darbhanga
Division:	Darbhanga-1	Length(Km):	1.20 km
Name of Road:	PWD Path to Shivram		
Scheme/Programme:	Maintenance		
Package No.	MR 3054	Road Id No.	31909200836
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank /slope & raincuts if any	Yes/No Yes
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U —
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U —
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U —
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No No.
3	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name: SHAMS AHMAD

Designation: A.E (RWD) Baheri Block
Darbhanga-01

31/12/2020

(Signature)