

Date of inspection : 02.12.2020		District: vaigstali	
Division : makur		Length (km):	
Name of the Road: NH-103 નીચે રીડીંગ રોડ		અનુબંધ મધ્ય વિદ્યાભાગ સી.ઈ. સી.ઈ. ભાગ	
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	Good Condition
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: RINIK KUMARI

DESIGNATION: J.E

(Signature)