FIELD INSPECTION REPORT

Date of Inspection : >	12/2020	District: Kaimur
Division: Bhathe	ia	Length (km): 7,0/m
Name of the Road: Ro	angarh to	Bajardihwa Roccof Bhagwan pu
Scheme/Programme:	MAINTENANCE	-
Package No.: MRC	3059)	Road Id No.: 10301400815
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

***************************************	The is a case of:	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	~S/U
d)	Road Camber	_S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Rowindon Kumar Showma DESIGNATION: A. E, Bheegwampur