

FIELD INSPECTION REPORT

Date of Inspection : 2.12.20	District: Kaimur
Division : Bhabua	Length (km): 11.480
Name of the Road: BHABUA HUDRA RD. TO GANGA PUR VIA BARRI BATH	
Scheme/Programme:	MAINTENANCE ✓
Package No.: MR (3054)	Road Id No.: 10301400825
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	✓ S/U NA
c)	Riding Quality	✓ S/U NA
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Nil

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Bhaskar
2.12.20
(Signature)

NAME: Ghosh Bhomshon Kumar
DESIGNATION: A.E