

FIELD INSPECTION REPORT

Date of Inspection: 2/12/2020 District: Palani
 Division: Road & Pavement Length (km): 1.02 km
 Name of the Road: PW 36 (Purana) Mandalam to Rathi Road Ghugalak Path
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/A
b)	Condition of Surfacing	S/A
c)	Riding Quality	S/A
d)	Road Camber	S/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (C/Pavement)	Yes/No
g)	Condition of Bank/slopes & cuttings if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in House pipe culverts including its painting	S/A/S/A
b)	Condition of Abutment & Wing walls, Slab in Box culverts	S/A/S/A
c)	Condition of cuttings/side approach for Bridges	S/A/S/A
3.	Road Furniture	
a)	Whether sign boards/indications/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of / F.P.C & any others	

Overall Rating

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

SRI

(Signature)

NAME

DATE/TIME