FIELD INSPECTION REPORT

Date o	f Inspection :	3/12/2020	District: Patna		
Division: Masaurte Length (km)			Length (km): 1-800 Km		
AND RESIDENCE AND RESIDENCE	SCHOOL SECTION AND ADDRESS OF THE PARTY OF T	II KADIRGAN	J' Patrito Harla to L	al bay Pat	
-	e/Programme:	MAINTENANCE			
Packag		TA	Road Id No.:		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
SI. No.	THE RESERVE OF THE PERSON NAMED IN	Parameters t		Remarks	
1.	Pavement				
a)	Road Junction condition			y S/U ~	
b)	Condition of Surfacing			S/U~	
0)	Riding Quality			S/U L	
d)	Road Camber			VS/U	
0)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			√Yes/No	
D	Contraction Joints provided or not (CC Pavement)			Ves/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Draining		A STATE OF THE STA		
a)	Condition of head walls in Hume pipe culverts including its painting			✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Faraltur				
.)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
THE REAL PROPERTY.	Compliance His	itory	All Maria Street Sections	力技術等	
CHEST SERVICE ST.	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	0

\$ 3/12/2020 (Signature)

Phinkar Prasa-

NAME:

Assistant Engineer

DESIGNATION: