## FIELD INSPECTION REPORT

		District: East cham	param
the State of the latest the latest terms.	1 /2/	Length (km): 5.85 Km	1
Division	the Road: Motilia	a Dhaka PINI Droad Patpas	149 mo
	Programme: MAINTI	ENANCE	0
Package		Road Id No.:	
Status o	Tal Declart Ongoing	/Completed/Under Maintenance	d
Work is	n case of: New Cor	inectivity/op gradation	Remarks
SI. No.	Par	ameters to be checked	Remarks
1.	Pavement	至 表现 其 (4)	
a)	Road Junction condition		US/0
b)	Condition of Surfacing		-8/U
c)	Riding Quality		_8/U
d)	Road Camber		/S/U
e)		defects such as visible cracks, exposed	Yes/No
f)		ided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slo	ope & raincuts if any	Yes/No
2.	Cross Drainage	A construction of the cons	
a)	Condition of head walls	s in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment	& Wing walls, Slab in RCC culverts	/S/SRI/U
c)	Condition of railings/sl	ab/approach for Bridges	/S/SRI/U
3.	Road Furniture		-
a)	Whether sign boards/ stones/Pavement road r	informatory/cautionary Board/km & 200m narkings are provided and maintained	Yes/No
4.	Compliance History	THE SECOND STATE OF SECOND STATE OF SECOND S	
a)	Status of ATR's & any	others	NIA

Overall Rating

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

330 m road, length damaged due to Flood-2020

(Signature)

NAME: Afray Ahmad

DESIGNATION: A-E