

FIELD INSPECTION REPORT

Date of Inspection: 03/12/20 District: MOTIHARI
 Division: MOTIHARI Length (km): 2.100
 Name of the Road: CHHAPRA BAHAS SUGALI ROAD TO KATHWALIYA
 Scheme Programme: MAINTENANCE (ld)
 Package No.: Road Id No.:

Status of the Project: Ongoing Completed Under Maintenance ✓

Work is a case of: New Connectivity Upgradation/Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	— S/U
c)	Riding Quality	— S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

100 meter length damaged due to Flood-2020
 which is already reported on MIS.

Rajendra
 03/12/20.
 (Signature)

NAME: Rajendra prasad yadav

DESIGNATION: AE

03/12/20
 J.E