

FIELD INSPECTION REPORT

Date of Inspection :	02/12/20	District:	MOTIHARI
Division :	MOTIHARI	Length (km):	6-10
Name of the Road:	NH 284 SUGAON TO GORIGAWAN VIA LAMONIA		
Scheme/Programme:	MAINTENANCE (old)		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance .		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'S'

30 meter length road surface damaged due to flood 2020. which is already reported on MIS.

[Signature]
02/12/20
J.E

[Signature]
02/12/20
(Signature) J.E

NAME: Rajendra. Prasad Yadav

DESIGNATION: J.E