

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: EAST CHAMPARAN	
Division : MOTIHARI		Length (km): 4.250 km	
Name of the Road: NH-28A BHELGA CHHARRA TO GOORAKI			
Scheme/Programme: MAINTENANCE - 3054 - MR OLD			
Package No.: MR OLD		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		COMPLETED	
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U - 5
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of Flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Finding :- Road damaged due to flood. Its report entry in FDR MIS. Motorable work done but pavement restoration is required.

NAME: AKHILESH PRASAD

DESIGNATION: A.E., Works & Division,

Banjaraya (Mothari Division)

NAME :- ABHIMANYU TANTI

DESIGNATION :- J.E., Banjaraya/KOTWA

(Signature)

3-12-2020

A.E.

Ans

03/12/2020

J.E.

Damaged due to flood.