

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: EAST CHAMPARAH
Division : MOTIHARI		Length (km): 6.970 km.
Name of the Road: MOTIHARI CHAMPARAH NH-28A TO HJG947 Jytna-janyew Ghat.		
Scheme/Programme: MAINTENANCE		
Package No.: MR 0LD		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance (COMPLETED)
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	
		Remarks

1.	Pavement	a) Road Junction condition	S/U-S
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S/U
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA
g)	Compaction of flank/slope & raincuts if any		Yes/No NA
2.	Cross Drainage	a) Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3.	Road Furniture		S/SR/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Finding:- Road damaged due to flood. Its report entry in FDR MIS. Motorable work done but permanent restoration is required.

NAME: AKHILESH PRASAD

DESIGNATION: A.E. Works Sub-Division, BANJARIAH. (MOTIHARI DIVISION)

NAME:- ABHIMANYU TANTI
DESIGNATION:- J.E., BANJARIAH/KATWA

Amf
03/12/2020
J E

(Signature)
03/12/2020
AE.

Damaged due to flood.