## FIELD INSPECTION REPORT

Date of I	nspection: 3	1/2/20 Dis	trict:	Mar	uada 5.090	
Division: Rajanti			ngth (km)	: 5	5.090	
Name of	the Road:  \	1131 to Kaziehak	via Am	2647		
	Programme:	MAINTENANCE				
Package No.:			ad Id No.		NO	
			npleted/Under Maintenance			
Work is	a case of:	New Connectivity/Up gradation/ Maintenance				
Sl. No.		Parameters to be el	hecked			Remarks
1.	Pavement	The second discount	Compa di		ilia denici	
a)	Road Junction condition				š/U	
b)	Condition of Surfacing				S/U	
c)	Riding Quality				š/U	
d)	Road Camber					S/U
æ)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)					Yes/No T
g)	Compaction of flank/slope & raincuts if any					Yes/No
2.	Cross Drains	Pe il		124 - K		
a)						S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U
c)	Condition of railings/slab/approach for Bridges					S/SRI/U
<b>3</b>	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
4.	Compliance I	listory				
a)	Status of ATR	's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) OZ

NAME: Vinay Wumar

DESIGNATION: JE