

FIELD INSPECTION REPORT

Date of Inspection: 02/12/21 District: Vaidhali
 Division: R.D. Vasipada Length (km): 2.20 KM
 Name of the Road: Pedduli to Saviga Path
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Upgrading/Completed/Under Maintenance
 Work is a case of: New/Extension/Upgradation/Maintenance

Sl. No. Parameters to be checked Remarks

1. Pavement

- a) Road Junction condition ☒ S
- b) Condition of Surfacing ☒ S
- c) Binding Quality ☒ S
- d) Road Carriageway ☒ S
- e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. ☒ Yes No
- f) Contraction Joints provided or not (CC Pavement) ☒ Yes No
- g) Compaction of flank/slope & raincuts if any ☒ Yes No

2. Cross Drainage

- a) Condition of head walls in Hume pipe culverts including its painting ☒ S/SRI/U
- b) Condition of Abutment & Wing walls, Slab in RCC culverts ☒ S/SRI/U
- c) Condition of railings/slab/approach for Bridges ☒ S/SRI/U

3. Road Furniture

- a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained. ☒ Yes No

4. Complaints History

- a) Status of ATR's & any others ☒ No

Overall Rating :

Satisfactory (S)

5

Satisfactory but requires Improvement (SRI)

—

Unsatisfactory (U)

—

NAME:

DESIGNATION

Signed