

FIELD INSPECTION REPORT

Date of Inspection: 02/12/20 District: Vashali
 Division: RWD Hazipur Length (km): 2.50 km
 Name of the Road: Sahdula to Kaidaiya
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed/Under Maintenance
 Work is a case of: New/Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SR
b)	Condition of Surfacing	SRU
c)	Riding Quality	SR
d)	Road Camber	SR
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SR/UR
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SR/UR
c)	Condition of railings/slab/approach for Bridges	SR/UR
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Comp'ts are History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRi)	-
Dissatisfactory (U)	-

NAME:

DESIGNATION

Signature