

FIELD INSPECTION REPORT

Date of Inspection: 05/12/20
 Division: 2122 Hapur
 District: Nishad
 Length (km): 4 km 40 m
 Name of the Road: Mangar (P. Mangar Path)
 Scheme Programme: MARRS
 Package No.:
 Road Id No.:
 Status of the Project: Ongoing / Completed / Under Maintenance
 Work is a case of: New / Extension / Rehabilitation / Maintenance

Sd No. Parameters to be checked Remarks

1 Pavement

- a) Road Surface condition Yes
- b) Condition of Surfacing Yes
- c) Riding Quality Yes
- d) Road Curves Yes
- e) Whether free from defects such as visible cracks exposed aggregates in case of CC Pavement Yes
- f) Contraction Joints provided or not (CC Pavement) Yes/No
- g) Compaction of flank/slope & raincuts if any Yes/No

2 Cross Drainage

- a) Condition of head walls in Hume pipe culverts including its painting No/SRI
- b) Condition of Abutment & Wing walls, Slab in RCC culverts No/SRI
- c) Condition of railings/slab/approach for Bridges No/SRI

3 Road Furniture

- a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No

4 Complaints History

- a) Status of ATR's & any others No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Dissatisfactory (U)

Signature
 Date: 05/12/20
 Ai

Sd/-

NAME:

ORGANIZATION