| Date of                | f Inspection :                | 02/12/2020                                 | District: Coton C                                | ,            |
|------------------------|-------------------------------|--|--|--------------|
| Divisio                |                               | repur                                      | Length (km): 1.000 Km                            |              |
| Name                   | of the Road: The              | nipur Bazar                                | to sorangpur latti.                              | L '          |
| Scheme                 | e/Programme:                  | MAINTENANCE                                | Spirer 1000                                      | ,            |
| Packag                 | ge No.:                       |  | Road Id No.:                                     |              |
| Status of the Project: |                               | Ongoing/Completed/Under Maintenance        |  |              |
| Work is a case of:     |                               | New Connectivity/Up gradation/ Maintenance |  |              |
| SI. No.                | Alle Carlot                   | Parameters to                              | be checked                                       | Remarks      |
|                        | Pavement                      |  |  |              |
| a)                     | Road Junction                 | condition                                  |  | <i>181</i> Ú |
| b)                     | Condition of S                | urfacing                                   |  | 18/U         |
| c)                     | Riding Quality                |  |  | <i>481</i> Ú |
| d)                     | Road Camber                   |  |  | 48/Ú         |
| e)                     | Whether free aggregates in ca | from defects such ase of CC Pavement.      | as visible cracks, exposed                       | Yes/No       |
| f)                     | Contraction Joi               | nts provided or not (C                     | CC Pavement)                                     | 1.Yes/No     |
| g)                     | Compaction of                 | flank/slope & raincut                      | s if any   | Yes/No       |
| 2:                     | Gross Dramag                  |  |  |              |
| a)                     | Condition of he               | ad walls in Hume pip                       | e culverts including its painting                | S/SRI/U      |
| b)                     | Condition of Ab               | outment & Wing wall                        | s, Slab in RCC culverts                          | S/SRI/U      |
| c)                     | Condition of rai              | lings/slab/approach fo                     | or Bridges                                       | S/SRI/U      |
| 3.                     | Road Furnitur                 |  |  |              |
|                        |                               |  | autionary Board/km & 200m rovided and maintained | LYes/No      |
| 4,                     | Complance His                 | noya take sa                               |  |              |
| a)                     | Status of ATR's               | & any others                               |  | 8            |
|                        |                               | · ·  |  |              |

Overall Rating

| Satisfactory (S)                            | S, |
|---|----|
| Satisfactory but requires Improvement (SRI) |    |
| Unsatisfactory (U)                          |    |

(Signature)

NAME: Nigmanand Mahto
Nigma
02/12

Scanned with CamScanner