

FIELD INSPECTION REPORT

Date of Inspection :	02/12/20	District:	Kaimur
Division :	Bhabhua	Length (km):	3.150 km
Name of the Road:	Bhabhua to Chand Pargra		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/2019-20/14	Road Id No.:	10301401007
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U- N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI -
Unsatisfactory (U)	X

[Signature]
02.12.20

(Signature)

NAME: Shashi Bhusha Pathak

DESIGNATION: JE