

# FIELD INSPECTION REPORT

Date of Inspection :	03/12/20	District:	Kaimur
Division :		Length (km):	
Name of the Road:	Lanka to Chand Dhrauli Prvd road		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/2019-20/14	Road Id No.:	10301402017
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO -

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	x
Unsatisfactory (U)	x

*[Signature]*  
03/12/20  
(Signature)

NAME: Shashi Bhushan Pathak  
DESIGNATION: JE