FIELD INSPECTION REPORT

	f Inspection:	3.12.20	District: Patris	
Division :			Length (km): 3.435M	
Name	of the Road:		otti Masaurhi	
	e/Programme:	MAINTENANCE	3054 Old	
Packag			Road Id No.:	
			d/Under Maintenance	
Work i	s a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.		Parameters to be checked		Remarks
1.	Pavement		t i i i i i i i i i i i i i i i i i i i	
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			√S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2 -	Cross Draining	e de la companya del companya de la companya del companya de la co	And the second s	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
ь)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			√Yes/No
4	Compliance His	More Property		Average Arter and
a) (Status of ATR's	& any others		NO

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ajay kumar ers
DESIGNATION: Elkur masurhis