FIELD INSPECTION REPORT

Date of I	Pate of Inspection: 02-12 - 2020 District:			-дауа	
Division: Jikori Length (km):			1.000		
Name of	the Road: Repo	sir of Road for gaz	ja Rafiganj Road Dumra More	1,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Scheme/l	Programme:	MAINTENANCE			
Package No.: Road Id No.:			1 - 1		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance		in a disconstitution of a
Sl. No.		Parameters	to be checked	TUL	Remarks
	Pavement			is to its vereinge	
u)	Road Junction condition				√S/U
b)	Condition of Surfacing			X	~ S/U
c)	Riding Quality			,	✓S/U
ď)	Road Camber			AND DESCRIPTION OF THE PARTY OF	∨S/U
e)	Whether free from defects such as visible cracks, eaggregates in case of CC Pavement.			kposed	- Yes/No
f)	Contraction Joints provided or not (CC Pavement)			,	— Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
e)	Condition of I	head walls in Hume	pipe culverts including its p	ainting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				-S/SRJ/U
c)	Condition of railings/slab/approach for Bridges				- S/SRI/U
3.	Road Furnitu	ire			
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained			200m	Yes/No
4.	Compliance History				The market of the new
a)	Status of ATE	C's & any others	M. Committee		
Overall Rating :				46	S
Overall reading .		Satisfactory (S			
. (t requires Improvement (\$	RI)	1/2
		Unsatisfactory	(U)		1000

Rama Arshad Alam
A.E. EE

NAME: