

FIELD INSPECTION REPORT

Date of Inspection :	2/12/2020	District:	Kaimgur
Division :	Mohaniya	Length (km):	3.720 KM.
Name of the Road:	Tairatha To Piparaghat		
Scheme/Programme:	MAINTENANCE		MR.
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Ongoing.
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	Work in progress	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

2/12/20
(Signature) J.E

NAME:

Santosh Kumar Tiwary