## FIELD INSPECTION REPORT

Date of Inspection: 02.12. No 20		District: Bhabhua (Kaiwar)	
Division: Blackhus		Length (km): 2.86	
Name of the Road: Ti	vito Hatta	Durgament Road	
Scheme/Programme: MAINTENANCE			
Package No.: MR-NI	2019-20/04	Road Id No.: 10301402031	
Status of the Project:   Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/		Up gradation/ Maintenance	
Sl. No.	Parameters to	be checked Remarks	

SI. No.	Parameters to be checked	Remarks
1	Pavement	建物重視
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	VS/U
d)	Road Camber	√S7U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	_

(Signature)

NAME: Birendra Kumar Singly DESIGNATION: A.E. Chaimpur