FIELD INSPECTION REPORT

Date of I	The same of the sa		TION REPORT	
Date of Inspection: 3 12 20 Division: Desper			District: PATHA	
Name of the Road: Leolipur Sadisopus Read to Harishan Fera Name			mana Ada	
Schom of	the Road: Lo		Length (km): 5.5 cm. Read to Harishan Pera No	
Packs	Programme:	MAINTENANCE		
C			Road Id No.:	
		Ongoing/Completed/Under Maintenance		
1.00.00		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
i ji	Pavement.	Carriers A Carriers A Carrier State of the Carrie		
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge	A CONTRACTOR OF THE	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4,	Compliance 1	lisjory		
a)	Status of ATR	's & any others		8 H
a)	Status of ATR	s & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	To see the second

word granted .

Balling.

312/2020 A.E. Maner

(Signature)

NAME:

DESIGNATION: