FIELD INSPECTION REPORT

Date of Inspection :	3/12/20	District: East Champoron		
Division: Passall	A second and a second and a second as the se	Length (km): 3.763 KM		
Name of the Road: Backeri potchor to Unchidih (Rompur)				
Scheme/Programme:	MAINTENANCE			
Package No.:	Road Id No.: 3170 8500 833			
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up	gradation/ Maintenance		

SLI	No. Parameters to be checked	Remarks		
J.	Pavement	alakung salahungkung laur rakun di sang pungungka sa sisatan sang di sang lauri sa sang sang di sang sang sang		
a) Road Junction condition		457 U		
b) Condition of Surfacing		5 /U		
c)				
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			
g)	g) Compaction of flank/slope & raincuts if any			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	VS/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N		
3.	Road Furniture			
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	VYcs/No		
	Compliance History	NA		
)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	and the second section of the section of the second section of the section of the second section of the second section of the second section of the sect
Unsatisfactory (U)	

NAME: Shashi Kant Sigh DESIGNATION: Junior Engineer