## FIELD INSPECTION REPORT

Dat	te of Inspection: 03-12-2020	District: East champar	as	
Division: Rayant		Length (km): 3.652 K	District: East champarais  Length (km): 3.652 KM	
Nan	ne of the Road: Kudas	itat to Ramnagar	and the second s	
Sch	eme/Programme: MAINTINA	NCI 3054	0/12-	
	age No.:	Road Id No.: 3/708500	84-	
resource to	us of the Project: Orgoing/Cor	npleted/Under Maintenance	And the second confidence and the second	
Wor	A CONTRACTOR OF THE PROPERTY O	tivity/Up gradation/ Maintenance	Ti an rales	
SLA	No. Parame	ters to be checked	Remarks	
1.	Pavement		-	
a)	Road Junction condition		N.AS/U	
b)	Condition of Surfacing		N. 8/U	
c)	Riding Quality		NAM	
d)	Road Camber		<b>S/U</b>	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No Yes/No Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)		Y cs/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		NS/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
	Compliance History			
	Status of ATR's & any others		N.A.	

Overall Rating :

Satisfactory (S)	(0)
Satisfactory but requires Improvement (SRI)	9
Unsatisfactory (U)	ngan madagangga miningga ang kalangga na kalangga na sa

NAME: ShyumSunder Rani DESIGNATION: A.E. Wine Sub-div. Chlouradano (Rayant)