FIELD INSPECTION DEPOR

		FIELD INSPEC	TION REPORT	
Date of I	nspection:	3 12/20	District: Nalanda	
Division: Bihar charill			Length (km): 1.10 Km	
rame of	the Road: Sar	e Nogwan Rous	dto konad Mor Via Gobar	Bigaha
Scheme/	rogramme:	MAINTENANCE	210 20144 1.00	-0
Package			Road Id No.:	
		Winder Maintenance Comple	interior	
			n graduit	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
	Riding Quality			S/U
c)				S/U
d)	Road Camber Whether free from defects such as visible cracks, exposed			Yes/No
e)	annual test in case of CC Payement.			
	Contraction Joints provided or not (CC Pavement)			Yes/No
n				Yes/No
g)	Compaction of flank/slope & raincuts if any			
2	Cross Drainage			S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			3/3100
c)	Condition of railings/slah/approach for Bridges			S/SRI/U
	Road Furniture			
3.	Road Purmiture			Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			TESTO
that the	Compliance I	History	The state of the s	The same of the same of the same
a)		s & any others		
٠,				

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Satisfactory but requires improvement	11
Unsatisfactory (U)	

(Signature)

NAME: Bijay kumur DESIGNATION: Executive Engineer

Scanned with CamScanner