

# FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Madhubani
Division : Madhubani	Length (km): 3.300 K.M.
Name of the Road: Sahpur Durg & Astham REB Sak to Paswan Tol	9 hote
Scheme/Programme: MAINTENANCE	Madhepura Mughahari Tol
Package No.: —	Road Id No.: —
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No YES
g)	Compaction of flank/slope & raincuts if any	Yes/No YES
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others Surface is good	NO ATR

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME: Ashok Prasad Singh  
DESIGNATION: AE, Pandaul

03/12/2020  
(Signature)

U  
AE  
03/12/2020  
Pandaul  
Mr. Manoj Kumar