

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Munger
Division :	Munger	Length (km):	0.550
Name of the Road:	Sotghana me Dhaneshwar kura ke ghar se Ramdeo Yadav		
Scheme/Programme:	MAINTENANCE M/R - 3054		
Package No.:		Road Id No.:	20803700849
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U S	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/S	
c)	Condition of railings/slab/approach for Bridges	S/SRI/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

MD. ALI AT ANWAR
NAME:

(Signature)
02/12/2020