FIELD INSPECTION REPORT

| Date of I | inspection: | 2.12,20 | District: 1/W my1 | |
|----------------------|----------------------------|--|-----------------------|---------|
| Division: Thubua Len | | | Length (km): 1.27 | |
| Name of | | | RA Rd. To PanchGANW | A |
| Scheme/ | Programme: | MAINTENANCE | | |
| Package | No.: MR-N | 12019-20/03 | Road Id No.: 10301502 | 027 |
| Status of | f the Project: | Ongoing/Complete | d/Under Maintenance | 021 |
| Work is a case of: | | New Connectivity/Up gradation/ Maintenance | | |
| Sl. No. | 10000 | Parameters t | o be checked | Remarks |
| 1. | Pavement | · · · · · · · · · · · · · · · · · · · | Samuel - Haly CER | 机研集器 |
| a) | Road Junction condition SA | | | SAUHA |
| b) | Condition of S | Surfacing | | A HUNS. |
| c) | Riding Quality | , | | S/UNA |

Whether free from defects such as visible cracks, exposed

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/contionary Board/km & 200m

Condition of Abutment & Wing wells, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Overall Rating

Road Camber

Cross Drainage .

Road Furniture

Compliance History

Status of ATR's & any others

aggregates in case of CC Pavement.

Contraction Joints provided or not (CC Pavement)

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

d)

c)

1)

g)

2.

a)

b)

c)

3.

a)

4.

B)

| Satisfactory (S) | |
|---|-------|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | Site. |

Blimby 2.12.20 (Signature)

MSTÜ

Yes/No

Yes/No

Yes/No

S/SRI/U

וחותאשי

SISRIVU

Yes/No

NO

NAME: Shimhi Bhowhan Kumay

DESIGNATION: A-C